

Important information regarding the delivery of prototypes

1. Conditions requiring the delivery of prototypes:

- Prior to serial production
- Product changes
- Production relocation
- Production interruption of more than one year
- Change of sub-suppliers

2. Required conditions for prototypes

- Must be mass produced
- Full testing based on drawing (compliance with the drawing)
- All characteristics have to be stamped on the WEBER original drawing
- Prototype test report according to VDA 2, submission level (see form „Initial sample test report“)
- Factory inspection certificate for material is required
- In case of subsequent prototypes, it is sufficient to indicate only the rejected values
- Must be permanently and clearly labelled as a prototype

3. Delivery:

- Clearly labelled as a prototype, visible from the outside (see „labelling of prototype deliveries“ form)
- All requirements listed in point 2 must be met

4. Release:

- In case of discrepancies, it is possible to release two subsequent prototypes
- All requirements must be fulfilled prior to release

5. Test equipment:

- Test equipment must be available and calibrated